From: **Bill Jacobs**

To: elray.roper@syngenta.com

Bcc: Meredith Laws

RE: Syngenta Multiplex Rodent bait station Subject:

Date: 09/11/2008 05:34 AM StnList042596.pdf Attachments:

The last dated and released version of the list appears in the attached .pdf file. Only one station was added to the list since it was appended to PR Notice 94-7. The list is currently undergoing revision. If the Multiplex is altered as we have discussed, it could appear on the new version that is expected to become available shortly or in a subsequent revision.



<elray.roper@syngenta.com>

<elray.roper@syngenta.com>

Bill Jacobs/DC/USEPA/US@EPA To

09/10/2008 04:55 PM

Subject RE: Syngenta Multiplex Rodent bait station

Bill: Thanks for the quick reply. Where can I get a copy of the most current list of "adequately protective" stations?

ElRay Roper

----Original Message----

From: Jacobs.Bill@epamail.epa.gov [mailto:Jacobs.Bill@epamail.epa.gov]

Sent: Wednesday, September 10, 2008 10:54 AM To: Roper ElRay USGR

Subject: Re: Syngenta Multiplex Rodent bait station

A reasonably firm lip on the bait tray insert (or on the station

is a design feature that is needed to meet criterion #6 for tamper-reisistant bait stations (see PR Notice 94-7). If such a feature

were added, the station could be added to the list of "adequately protective" units. The units listed there are bait stations that are sold empty. The testing that was done on the unit with dogs and children addressed issues related to other critera, principally #2 & #4, and would not have to be repeated.

The center rod position would not necessarily have to be removed, but instructions accompanying the unit should advise against using the center rod position when the station is deployed in areas where young children (under 6 years old) are likely to be present. Statistically the present design passed the child test. It's just that the 2 kids Statistically,

were able to touch the bait contacted bait that was on the center rod.

Keep in mind that the above discussions pertain to the marketing of

station in the "empty" condition (i.e., without bait packaged in or with

the unit). If the station were sold as part of a ready-to-use bait-station product, dog and child tests with unsecured units would have to be run if you desired to have it labeled as a Tier 1 or Tier 2 product. For Tier 3, child testing with unsecured units would be needed. Adult-utility testing would be needed for Tiers 1, 2, or 3. If you elect to modify the mold for the bait station to add a lip or remove the center rod position, you might also consider beefing up the hinge arrangement that holds the lid to the base and perhaps providing additional overlap to the locking mechanism. Although I rated the current and original designs sufficient in those areas, they are potential weak points relative to other components of the product's design. I have received "unsolicited feedback" to the effect that the lids on locked units can be lifted without need to use the special tool

by simply pulling up hard on the tab. That was not my experience when \bar{x}

evaluated the original design in 2003 or the current design in 2007. However, I did find that units would not fully lock unless the lid was pushed down until a distinctly audible "snap-to" sound was heard. A unit closed not quite to the "snap-to" point may appear to be locked but

literature should indicate how to confirm that the locking mechanism is fully engaged.

<elray.roper@syn

genta.com>

To

09/10/2008 11:58 Bill Jacobs/DC/USEPA/US@EPA

AM

CC

Subject

bait.

station

Syngenta Multiplex Rodent

Bill:

Last year when we were in Hawaii together we discussed what modifications would need to be made to the Multiplex Rodent bait station

so that it could pass the $\ensuremath{\mathsf{EPA}}$ Tamper resistant guidelines for child resistance.

Syngenta asked if we put a lip on the insertable bait tray would that meet the requirement in the assessment to add a lip so bait crumbs would not fall out of the station.

In addition we would need to remove the center bait rod position so a child could not reach into the station and touch the bait.

If these two modifications are made will the bait station, in your opinion, meet the tamper resistant guidelines without being retested?